

4-11-2000

## DDASaccident338

Humanitarian Demining Accident and Incident Database  
*AID*

Follow this and additional works at: <https://commons.lib.jmu.edu/cisr-globalcwd>

 Part of the [Defense and Security Studies Commons](#), [Peace and Conflict Studies Commons](#), [Public Policy Commons](#), and the [Social Policy Commons](#)

---

### Recommended Citation

Database, Humanitarian Demining Accident and Incident, "DDASaccident338" (2000). *Global CWD Repository*. 538.  
<https://commons.lib.jmu.edu/cisr-globalcwd/538>

This Other is brought to you for free and open access by the Center for International Stabilization and Recovery at JMU Scholarly Commons. It has been accepted for inclusion in Global CWD Repository by an authorized administrator of JMU Scholarly Commons. For more information, please contact [dc\\_admin@jmu.edu](mailto:dc_admin@jmu.edu).

# DDAS Accident Report

## Accident details

<b>Report date:</b> 19/05/2006	<b>Accident number:</b> 338
<b>Accident time:</b> 14:30	<b>Accident Date:</b> 11/04/2000
<b>Where it occurred:</b> Demining NGO sub-office, Herat,	<b>Country:</b> Afghanistan
<b>Primary cause:</b> Management/control inadequacy (?)	<b>Secondary cause:</b> Inadequate training (?)
<b>Class:</b> Handling accident	<b>Date of main report:</b> [No date recorded]
<b>ID original source:</b> No: MI 03/2000	<b>Name of source:</b> IGM
<b>Organisation:</b> Name removed	
<b>Mine/device:</b> Ordnance	<b>Ground condition:</b> not applicable
<b>Date record created:</b> 21/02/2004	<b>Date last modified:</b> 21/02/2004
<b>No of victims:</b> 2	<b>No of documents:</b> 1

## Map details

<b>Longitude:</b>	<b>Latitude:</b>
<b>Alt. coord. system:</b>	<b>Coordinates fixed by:</b>
<b>Map east:</b>	<b>Map north:</b>
<b>Map scale:</b> not recorded	<b>Map series:</b>
<b>Map edition:</b>	<b>Map sheet:</b>
<b>Map name:</b>	

## Accident Notes

inadequate investigation (?)  
inadequate medical provision (?)  
safety distances ignored (?)  
inadequate training (?)

## Accident report

Access to the accident data was denied by the MAC programme manager. A brief summary of the accident was provided by a professional researcher who had access to the original documents. That summary is reconstructed here.

No formal accident investigation was found in the MAC files.

During supervision of demining activities in Shin Dand district of Farah Province, Victim No.1 found an unknown device (probably a warhead) on 10<sup>th</sup> April 2000. He was the Assistant

operations officer. He wanted to investigate the device further, so took it to Herat. The next day, together with a "radio mechanic" he took it into the office and attempted to defuse and dismantle it. It exploded in the office. The two men died immediately. Their injuries were not recorded.

No other details were found on file.

### Victim Report

<b>Victim number:</b> 425	<b>Name:</b> Name removed
<b>Age:</b>	<b>Gender:</b> Male
<b>Status:</b> supervisory	<b>Fit for work:</b> DECEASED
<b>Compensation:</b> not made available	<b>Time to hospital:</b> not recorded
<b>Protection issued:</b> Not recorded	<b>Protection used:</b> not recorded

#### Summary of injuries:

FATAL

COMMENT

Various extreme injuries - immediately fatal. No medical report was made available.

### Victim Report

<b>Victim number:</b> 426	<b>Name:</b> Name removed
<b>Age:</b>	<b>Gender:</b> Male
<b>Status:</b> supervisory	<b>Fit for work:</b> DECEASED
<b>Compensation:</b> not made available	<b>Time to hospital:</b> not recorded
<b>Protection issued:</b> Not recorded	<b>Protection used:</b> not recorded

#### Summary of injuries:

FATAL

COMMENT

Various extreme injuries - immediately fatal. No medical report was made available.

### Analysis

The primary cause of this accident is listed as a "*Management/control inadequacy*" because a senior supervisor acted in breach of basic safety SOPs and caused the accident. His selection and training is a management responsibility. His actions imply that he may not have been appropriately trained, so the secondary cause is listed as "*Inadequate training*".

The failure of the MAC to carry out an accident investigation may have been because the accident did not occur while in the mined area. However, it occurred to a demining group under their control that was supposed to operate using UN MAC imposed SOPs. The victims were engaged in rendering safe an item from the mined area, so were technically undertaking

a working task. UXO are often moved before being destroyed. The fact that it was moved to an unauthorised area (the group's office) did not remove the MAC's obligation to carry out an investigation.

The failure of the MAC to allow access to accident reports means that the report made here is acknowledged to be unsatisfactory. It will be revised if access to other documents is ever allowed. The failure of the MACC to act with transparency is bound to raise questions over what they have to hide.