

10-14-2008

# DDASaccident654

Humanitarian Demining Accident and Incident Database  
*AID*

Follow this and additional works at: <https://commons.lib.jmu.edu/cisr-globalcwd>

 Part of the [Defense and Security Studies Commons](#), [Peace and Conflict Studies Commons](#), [Public Policy Commons](#), and the [Social Policy Commons](#)

---

## Recommended Citation

Database, Humanitarian Demining Accident and Incident, "DDASaccident654" (2008). *Global CWD Repository*. 853.  
<https://commons.lib.jmu.edu/cisr-globalcwd/853>

This Other is brought to you for free and open access by the Center for International Stabilization and Recovery at JMU Scholarly Commons. It has been accepted for inclusion in Global CWD Repository by an authorized administrator of JMU Scholarly Commons. For more information, please contact [dc\\_admin@jmu.edu](mailto:dc_admin@jmu.edu).

# DDAS Accident Report

## Accident details

<b>Report date:</b> 05/03/2011	<b>Accident number:</b> 654
<b>Accident time:</b> 09:45	<b>Accident Date:</b> 14/10/2008
<b>Where it occurred:</b> AF/2801/28726/MF 105, Ghulghula Village, Center District, Bamyan Province	<b>Country:</b> Afghanistan
<b>Primary cause:</b> Field control inadequacy (?)	<b>Secondary cause:</b> Inadequate training (?)
<b>Class:</b> Other	<b>Date of main report:</b> Not recorded
<b>ID original source:</b> DA36	<b>Name of source:</b> UNMACCA
<b>Organisation:</b> [Name removed]	
<b>Mine/device:</b> AP blast (unrecorded)	<b>Ground condition:</b> not recorded
<b>Date record created:</b>	<b>Date last modified:</b> 05/03/2011
<b>No of victims:</b> 1	<b>No of documents:</b> 1

## Map details

<b>Longitude:</b>	<b>Latitude:</b>
<b>Alt. coord. system:</b> Not recorded	<b>Coordinates fixed by:</b>
<b>Map east:</b>	<b>Map north:</b>
<b>Map scale:</b>	<b>Map series:</b>
<b>Map edition:</b>	<b>Map sheet:</b>
<b>Map name:</b>	

## Accident Notes

inadequate investigation (?)

inadequate area marking (?)

inadequate training (?)

protective equipment not worn (?)

visor not worn or worn raised (?)

## Accident report

The only report of this accident that has been made available to date was in a UNMACCA EXCEL spreadsheet. Text in square brackets [ ] is editorial. This record will be revised if more information is made available.

The EXCEL summary is reproduced below, edited for anonymity.

No.# Accident: DA36

Demining group: [Name removed]

Date of Accident: 14<sup>th</sup> October 2008 09:45 AM

IMSMA ID: CA-188

Accident/Incident: Demining Accident

Name: [The Victim]

Type of Casualty: Fatal

Type of injury: Died

Title: Deminer

Team No: DT 23

Task No: AF/2801/28726/MF 105

Activity of Victim during accident: Operations

Type Device: Mine

Equipment Damaged: [None]

Village, District, Province: Ghulghula Village, Center District, Bamyan Province

Investigation Completed Y/N: Y

Action Taken by NGOs (Y/N): Y

BOI Conclusions:

It is the BOI conclusion that the deminer, [the Victim], was not clearly marking his lane progressively throughout the course of the day. He has moved back into his clearance lane during a break period, without wearing his PPE and helmet, to place a marking stone. He has not wanted to get too close to the unsafe area and has leant forward and thrown the marking stone forward to mark the lane. This stone has landed on a mine with the detonation causing the stones to be thrown up from the blast and inflicting the injuries that have resulted in his death. It seems that the poor supervision and carelessness of deminer himself are the contributing factors to the accident.

### Victim Report

<b>Victim number:</b> 837	<b>Name:</b> [Name removed]
<b>Age:</b>	<b>Gender:</b> Male
<b>Status:</b> deminer	<b>Fit for work:</b> DECEASED
<b>Compensation:</b> Not made available	<b>Time to hospital:</b> Not recorded
<b>Protection issued:</b> Not recorded	<b>Protection used:</b> Not recorded

#### Summary of injuries:

FATAL

COMMENT: Deminer died. No details of injuries were recorded.

No Medical report was made available.

## **Analysis**

The primary cause of this accident is listed as a *Field Control Inadequacy* because the investigators identified this as a fault, and because the Victim was allowed to work without marking appropriately and then return to the hazardous area without wearing PPE. The secondary cause is listed as *Inadequate training* because, presumably, the Victim did not understand the risk that he was running.

The Victim cannot have “thrown” the stone very far in front of him because the AP blast mine must have detonated very close to him in order for it to inflict fatal injuries.

The “Inadequate investigation” listed under notes refers to the absence of a full accident report. The UN supported MACCA has failed to make these widely available for some years in contravention of the requirements of the IMAS. The failure of the UN to share the Afghan investigators’ work with others is regrettable.