

10-20-2003

## DDASaccident518

Humanitarian Demining Accident and Incident Database  
*AID*

Follow this and additional works at: <https://commons.lib.jmu.edu/cisr-globalcwd>

 Part of the [Defense and Security Studies Commons](#), [Peace and Conflict Studies Commons](#), [Public Policy Commons](#), and the [Social Policy Commons](#)

---

### Recommended Citation

Database, Humanitarian Demining Accident and Incident, "DDASaccident518" (2003). *Global CWD Repository*. 717.  
<https://commons.lib.jmu.edu/cisr-globalcwd/717>

This Other is brought to you for free and open access by the Center for International Stabilization and Recovery at JMU Scholarly Commons. It has been accepted for inclusion in Global CWD Repository by an authorized administrator of JMU Scholarly Commons. For more information, please contact [dc\\_admin@jmu.edu](mailto:dc_admin@jmu.edu).

# DDAS Accident Report

## Accident details

<b>Report date:</b> 27/01/2008	<b>Accident number:</b> 518
<b>Accident time:</b> Not made available	<b>Accident Date:</b> 20/10/2003
<b>Where it occurred:</b> Not made available	<b>Country:</b> Cambodia
<b>Primary cause:</b> Unavoidable (?)	<b>Secondary cause:</b> Management/control inadequacy (?)
<b>Class:</b> Excavation accident	<b>Date of main report:</b> Not made available
<b>ID original source:</b> None	<b>Name of source:</b> MAGUK MB
<b>Organisation:</b> [Name removed]	<b>Ground condition:</b> hidden root mat
<b>Mine/device:</b> PMN AP blast	<b>Date last modified:</b> 27/01/2008
<b>Date record created:</b>	<b>No of documents:</b> 1
<b>No of victims:</b> 1	

## Map details

<b>Longitude:</b>	<b>Latitude:</b>
<b>Alt. coord. system:</b>	<b>Coordinates fixed by:</b>
<b>Map east:</b>	<b>Map north:</b>
<b>Map scale:</b>	<b>Map series:</b>
<b>Map edition:</b>	<b>Map sheet:</b>
<b>Map name:</b>	

## Accident Notes

inadequate investigation (?)  
visor not worn or worn raised (?)  
incomplete detonation (?)

## Accident report

Details of this accident have been withheld by the demining NGO that employed the Victim. A spreadsheet including the Victim's name and very brief details of the accident was made available in 2007. Some details can be inferred from the information released. For example, the limited injury implies that the victim's PPE was being worn in the correct manner.

This entry will be expanded if access to the report of the investigation is made available in future.

The spreadsheet data is reproduced below, edited for anonymity.

“Date and country. [Name removed] - Deminer slight injuries to forehead and face, no permanent injuries. PMN mine detonated but didn't fully function as designed. Mine detonated whilst excavating around bamboo root in ground.”

## Victim Report

<b>Victim number:</b> 680	<b>Name:</b> [Name removed]
<b>Age:</b>	<b>Gender:</b> Male
<b>Status:</b> deminer	<b>Fit for work:</b> presumed
<b>Compensation:</b> Not made available	<b>Time to hospital:</b> Not made available
<b>Protection issued:</b> Not recorded	<b>Protection used:</b> Not made available

### Summary of injuries:

minor Face

minor Head

COMMENT: No Medical report was made available.

### Analysis

The primary cause of this accident is listed as a “Field control inadequacy” because the injuries to the forehead imply that the visor was worn raised and this error was not corrected.

The secondary cause is listed as a “Management control inadequacy” because the management of the demining group declined to make the accident details available. Although this is sometimes done to protect the Victims, in this case the Victim's name was among the limited detail made available. It is possible that the managers have chosen to avoid transparency because they are afraid that the circumstances of the accident would reflect badly on their organisation.