James Madison University
JMU Scholarly Commons

Global CWD Repository

Center for International Stabilization and Recovery

6-12-2008

DDASaccident648

HD-AID Humanitarian DeminingAccident and Incident Database

Follow this and additional works at: https://commons.lib.jmu.edu/cisr-globalcwd

Part of the Defense and Security Studies Commons, Peace and Conflict Studies Commons, Public Policy Commons, and the Social Policy Commons

Recommended Citation

HD-AID, "DDASaccident648" (2008). *Global CWD Repository*. 847. https://commons.lib.jmu.edu/cisr-globalcwd/847

This Other is brought to you for free and open access by the Center for International Stabilization and Recovery at JMU Scholarly Commons. It has been accepted for inclusion in Global CWD Repository by an authorized administrator of JMU Scholarly Commons. For more information, please contact dc_admin@jmu.edu.

DDAS Accident Report

Accident details	-
Report date: 05/03/2011	Accident number: 648
Accident time: 08:45	Accident Date: 12/06/2008
Where it occurred: MF.048, Jamchi Village, Kapisa Province	Country: Afghanistan
Primary cause: Field control inadequacy (?)	Secondary cause: Inadequate training (?)
Class: Handling accident	Date of main report: Not recorded
ID original source: DA15	Name of source: UNMACCA
Organisation: [Name removed]	
Mine/device: detonator (fuze)	Ground condition: not recorded
Date record created:	Date last modified: 05/03/2011
No of victims: 1	No of documents: 1

Map details

Longitude:	Latitude:
Alt. coord. system:	Coordinates fixed by:
Map east:	Map north:
Map scale:	Map series:
Map edition:	Map sheet:
Map name:	

Accident Notes

inadequate investigation (?)

inadequate training (?)

Accident report

The only report of this accident that has been made available to date was in a UNMACA EXCEL spreadsheet. Text in square brackets [] is editorial. This record will be revised if more information is made available.

The EXCEL summary is reproduced below, edited for anonymity.

S. # 15 No.# Accident: DA15 Demining group: [Demining group] Date of Accident: 12th June 2008, 08:45 IMSMA ID: CA-189 Accident/Incident: Demining accident Name: [The Victim] Type of Casualty: Injured Type of injury: Injuries on his fingers Title: Deminer Team No:DT-28 Task No: MF.048 Activity of Victim during accident: Prodding Type Device: detonator Equipment Damaged: [None] Village, District, Province: Jamchi Village, Kapisa Province Investigation Completed Y/N: Action Taken by NGOs (Y/N):

BOI Conclusions:

1. A detonator blast caused the accident. The deminer has detected an active detonator in his clearance lane and has pressed it by his left hand fingers which subsequently the detonator exploded and the deminer fingers were seriously injured.

2. Carelessness of the deminer is to be deemed a major contributing factor to this accident, as instead of informing the section leader, he disturbed the hazard object and caused it to be exploded.

Victim Report

Victim number: 831	Name: [Name removed]
Age:	Gender: Male
Status: deminer	Fit for work: not known
Compensation: Not made available	Time to hospital: Not made available
Protection issued: Not recorded	Protection used: Not made available

Summary of injuries:

INJURIES: severe Fingers

COMMENT: No Medical report was made available.

Analysis

The primary cause of this accident is listed as a *Field Control Inadequacy* because the Victim was acting in breach if SOPs and his error was not corrected. The secondary cause is listed as *Inadequate training* because he may not have recognised that the object was dangerous.

The "Inadequate investigation" listed under notes refers to the absence of a full accident report. The UN supported MACCA has failed to make these widely available for some years in contravention of the requirements of the IMAS. The failure of the UN to share the Afghan investigators' work with others is regrettable.